

M/s. Dooall Corpro India Pvt Ltd.
No. 21, Damji Shamji Industrial Estate,
L. B. S. Marg, Vikhroli West
Mumbai - 400083, Maharashtra, India

March 26, 2017

Your ref. No. & letter dated on June 10, 2016.

Our Job NO. IN/ASK -27/16-17

Dear Sir

Subject: - Salt Spray Testing of the coated panels

5. System


DL-ZS + Modpoxy ST middle coat + Modpoxy GF intermediate coat + Modithane top coat

Total DFT - 375 microns (75 + 125 + 125 + 50)

Please find hereby the test results of coated panels submitted to us.

Test parameter	Standard	Specification	Results
Salt spray test @ 4000 hrs	ASTM B 117	Passes	Passes no Blistering or corrosion observed

Test results pertain to the samples submitted to us.



A.S. Khanna

Prof. A. S. KHANNA

Corrosion Science & Engineering
Dept. of Met. Engg. & Material Science
I.I.T. BOMBAY
Powai, Mumbai - 400 076.